



PRESSURE DROP CURVES FOR "Y" TYPE STRAINERS





Notes:

These charts apply to clean perforated baskets used for water service.
For mesh lined screens from 20 - 100 mesh, multiply by 1.25

FABROTECH INDUSTRIES, INC

2089 NINTH AVENUE, RONKONKOMA, NEW YORK 11779
 TEL: (631) 467-2040 FAX: (631) 467-2196 e-mail: fabrotec@aol.com
www.fabrotech.com

PRESSURE DROP CURVES FOR "Y" TYPE STRAINERS



Notes:

These charts apply to clean perforated baskets used for water service.
For mesh lined screens from 20 - 100 mesh, multiply by 1.25

FABROTECH INDUSTRIES, INC

2089 NINTH AVENUE, RONKONKOMA, NEW YORK 11779

TEL: (631) 467-2040 FAX: (631) 467-2196 e-mail:fabrotec@aol.com

www.fabrotech.com